

# Service Campaign Bulletin

Campaign No. 2013090003, **October** 2013

Revision	Date	Purpose
A	10/04/13	Update to work Procedure
-	09/20/13	Initial release

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 906, Model Year 2013**  
**Update Engine Control Module Software**

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz and Freightliner Sprinter vehicles, has determined that the engine control module software does not correspond to current production configuration. An authorized Mercedes-Benz or Freightliner dealer will update the engine control module software at the next workshop visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 17,888 vehicles are affected.

Order No. V-SC-2013090003

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

**Procedure****Note:**

- Use DAS/Xentry 09/10-13 with all the latest Add-ons, specifically Add-on 3110, (or higher) or 09/10-13 release of Fleet Shell (FedEx® and other large fleets only) Follow the steps exactly as described in DAS/Xentry.
  - Connect battery charger (battery voltage >12.5V).
  - Ensure all electrical consumers are switched-off.
  - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk.
  - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. Update engine control unit software:  
Control units / Drive / CDI control unit CR60 / Control unit adaptations / Control unit programming.
  2. Follow on-screen instructions.

**Note:**

Please verify CDI software number change after performing the software update.

**Warranty Information**

**Operation:** Update engine control module software (with DAS connected) (02-8532)

Damage Code	Operation Number	Labor Time (hrs.)
49 920 71 8	02-8532	0.4

**Note**

Operation Number labor times are subject to change.