



**Internal notification for: G_0000158697 11175A - Special Coverage - Shift
Lever May Not Display Correct Gear - Revised**
gm_gmssg_q01

02/11/2013 01:50 PM

2 attachments



11175A bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 02/11/2013

Ref. number: Service / Field Action / G_0000158697

Subject: 11175A - Special Coverage - Shift Lever May Not Display Correct Gear - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2910
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 11, 2013

Subject: 11175A - Special Coverage
Shift Lever May Not Display Correct Gear
Revised Service Procedure

Models: 2007-2008 Saturn AURA Equipped with 4-Speed Automatic
Transmission (ME7/MN5)

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The service procedure in this bulletin has been revised to include the installation of a cable kit (clam shell).
Please discard all copies of bulletin 11175.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

11175A bulletin.pdf Acrobat PDF (318.6KB)
11175A bulletin

name:

[

Phone:

Intended General Manager, Parts & Service Director, Parts Manager, Service Advisor, Used Vehicle