



Internal notification for: G_0000167211 12190A - Fuel Odor or Spotting on Ground - Inspect Fuel Pump Module - Revised
gm_gmssg_q01

06/04/2013 05:55 AM

2 attachments



12190A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 6/04/2013

Ref. number: Service / Field Action / G_0000167211

Subject: 12190A - Fuel Odor or Spotting on Ground - Inspect Fuel Pump Module - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2976
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 4, 2013

Subject: 12190A - Safety Recall
Fuel Odor or Spotting on Ground - Inspect Fuel Pump Module
Revised to Include Equinox/Torrent Information

Models: 2007 Chevrolet Equinox and Pontiac Torrent Originally Sold or
Currently Registered in Arizona, California, Nevada, or Texas

2007 Chevrolet Cobalt and Pontiac G5 Originally Sold or Currently
Registered in Arizona, California, Florida, Nevada, or Texas

2008 Chevrolet Cobalt and Pontiac G5 Originally Sold or Currently
Registered in Arizona

2009 Chevrolet Cobalt and Pontiac G5 Originally Sold or Currently
Registered in Arkansas, Arizona, California, Nevada, Oklahoma,
or Texas

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

Due to part availability, this bulletin was administered in phases. The first phase included the Chevrolet Cobalt and Pontiac G5 vehicles. This second and final phase will include the Chevrolet Equinox and Pontiac Torrent vehicles.

The service procedure has also been revised to include the installation of the Recall Identification Label and the completion of a "Proof of Correction" certificate for all vehicles registered in California.

Please discard all copies of bulletin 12190.