

Internal notification for: G_0000158965 12265 - Service Update - Automatic Radio Volume Increase and/or Radio Control Assembly Buttons Not **Operating as Designed** gm_gmssg_q01

02/22/2013 06:27 AM

3 attachments

PDF

12265 bulletin.pdf 12265 Involved VIN List.xls GM Style Sheet.css

Your email client does not support HTML messages

Date: 02/22/2013

Ref. number: Service / Field Action / G_0000158965

Subje 12265 - Service Update - Automatic Radio Volume Increase and/or Radio Control Assembly Buttons ct: Not Operating as Designed

GM CUSTOMER CARE AND AFTERSALES DCS2913 **URGENT - DISTRIBUTE IMMEDIATELY**

Date: February 22, 2013

Subject: 12265 - Service Update Bulletin Automatic Radio Volume Increase and/or Radio Control Assembly Buttons Not Operating as Designed

Models: 2013 Cadillac ATS, SRX, XTS

To: All Cadillac Dealers

General Manager, Service Advisor, Service Manager, Parts and Attention: Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Service Update Bulletin 12265 today. The total number of U.S. vehicles involved is approximately 15,000. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated February 26, 2013. A list of involved vehicles is attached to this message.

Service Update Bulletin (SUB) Information Link The SUB Information Link in GlobalConnect will be updated in the near future.

END OF MESSAGE GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s): 212265 bulletin.pdf Acrobat PDF (113.9KB) 12265 bulletin