

GM CUSTOMER CARE AND AFTERSALES
DCS2993
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 27, 2013

Subject: 12180C – Safety Recall
Driver Door Switch Short Circuit
Revised Service Procedure

Models: 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL; 2006-07 Buick
Rainier, Chevrolet TrailBlazer, GMC Envoy

To: All Buick, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

Bulletin 12180C has been revised to include an inspection and service procedure
overview in the service procedure. Please discard all copies of bulletin 12180B.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES