



Internal notification for: G_0000172843 12180E - Safety Recall - Driver Door Switch Short Circuit - Revised
 gm_gmssg_q01

08/13/2013 03:35 PM

2 attachments



12180E bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 8/13/2013 Ref. number: Service / Field Action / G_0000172843
 Subject: 12180E - Safety Recall - Driver Door Switch Short Circuit - Revised

GM CUSTOMER CARE AND AFTERSALES
 DCS3030
 URGENT - DISTRIBUTE IMMEDIATELY

Date: August 13, 2013
 Subject: 12180E - Safety Recall
 Driver Door Switch Short Circuit
 Service Repair Video Available
 Models: 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL; 2006-07 Buick Rainier, Chevrolet TrailBlazer, GMC Envoy
 To: All Buick, Chevrolet, and GMC Dealers
 Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

The Service Procedure section has been revised to inform technicians that a video that demonstrates the vehicle repair is now available at www.centerlearning.com. All technicians should review this video immediately. Please discard all copies of bulletin 12180D.

END OF MESSAGE
 GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12180E bulletin.pdf Acrobat PDF (1.405MB)
 12180E bulletin

name:

Department: Service - Brand Quality

Phone:

Intended General Manager, Parts & Service Director, Parts Manager, Service Advisor, Service roles: Manager, Used Vehicle Sales Manager, Warranty Administrator