



Internal notification for: G_0000158394 12261A - Safety Recall - Intermittent Airbag Warning Light Illuminated - Replace Steering Wheel Airbag Coil - Revised

gm_gmssg_q01

02/06/2013 02:45 PM

2 attachments



12261A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 02/06/2013

Ref. number: Service / Field Action / G_0000158394

Subje 12261A - Safety Recall - Intermittent Airbag Warning Light Illuminated - Replace Steering Wheel

ct: Airbag Coil - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2904
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 6, 2013

Subject: 12261A - Safety Recall
Intermittent Airbag Warning Light Illuminated - Replace Steering Wheel Airbag Coil
Revised Part Information Section

Models: 2012 Buick Verano and Chevrolet Camaro, Cruze, and Sonic

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

The part numbers for the Chevrolet Cruze have been revised in the Part Information section. Please discard all copies of bulletin 12261.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12261A bulletin.pdf Acrobat PDF (218.2KB)

12261A bulletin

name:

C

t:

Phone: