



Internal notification for: G_0000172077 13136A - Safety Recall - Loss of Battery Charge - Inspect Generator Control Module - Revised
gm_gmssg_q01

08/01/2013 02:31 PM

2 attachments



13136A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 8/01/2013

Ref. number: Service / Field Action / G_0000172077

Subject: 13136A - Safety Recall - Loss of Battery Charge - Inspect Generator Control Module - Revised

**GM CUSTOMER CARE AND AFTERSALES
DCS3023
URGENT - DISTRIBUTE IMMEDIATELY**

Date: August 1, 2013

Subject: 13136A - Safety Recall
Loss of Battery Charge - Inspect Generator Control Module
Revised Part Information and Service Procedure Sections

Models: 2012-13 Buick LaCrosse, Regal; 2013 Chevrolet Malibu ECO
Equipped with e/Assist

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager, and Warranty Administrator

Parts required for safety recall 13136 have been removed from Product Quality Center (PQC) restriction. Additional part numbers and a part inspection procedure have been added to this bulletin. Please discard all copies of bulletin 13136.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13136A bulletin.pdf Acrobat PDF (353.2KB)
13136A bulletin

From:

Name:

Department: Service - Brand Quality

Phone:

Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,
roles: Service Advisor, Service Manager, Used Vehicle Sales Manager, Warranty Administrator