



**Internal notification for: G_0000170561 13186 - Service Update Bulletin -
Incorrect Battery Current Sensor on Negative Battery Cable Assembly -
Revised VIN List**
gm_gmssg_q01

07/10/2013 03:03 PM

2 attachments



13186 Inventory VINs.-Revised 7-10-13.xls



GM Style Sheet.css

Your email client does not support HTML messages

Date: 7/10/2013 Ref. number: Service / Field Action / G_0000170561
Subject: 13186 - Service Update Bulletin - Incorrect Battery Current Sensor on Negative Battery Cable
Assembly - Revised VIN List

**GM CUSTOMER CARE AND AFTERSALES
DCS3000
URGENT - DISTRIBUTE IMMEDIATELY**

Date: July 10, 2013
Subject: 13186 - Service Update Bulletin
Incorrect Battery Current Sensor on Negative Battery Cable Assembly
Revised VIN List
Models: 2013 Cadillac Escalade, Escalade ESV; Chevrolet Tahoe, Suburban;
GMC Yukon, Yukon XL; 2013-14 Chevrolet Captiva, Captiva Sport;
2014 Chevrolet Silverado, GMC Sierra
To: All Cadillac, Chevrolet, and GMC Dealers
Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator


General Motors announced Service Update Bulletin 13186 on June 26, 2013. A VIN list of involved vehicles in dealer inventory was attached to the message. The list included 3/4 and 1 ton vehicles, in error. We are in the process of manually closing these in the "Investigate Vehicle History" (IVH) screen.

Attached to this message is a revised VIN list of involved vehicles in dealer inventory.

Please discard all copies of the previous involved VIN list that was sent to you and begin using the attached list to inspect and repair involved vehicles in dealer inventory.

**END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES**

Message Attachment(s):

 13186 Inventory VINs.-Revised 7-10-13.xls MS Excel Worksheet 8.0-2003 (Windows) (335.5KB)
13186 Revised Inventory VIN List-7-10-13