



Internal notification for: G_0000158994 12238D - Service Update - Loss of Battery Charge - Inspect Generator Control Module - Revised
gm_gmssg_q01

02/13/2013 03:14 PM

2 attachments



12238D bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 02/13/2013

Ref. number: Service / Field Action / G_0000158994

Subject: 12238D - Service Update - Loss of Battery Charge - Inspect Generator Control Module - Revised

**GM CUSTOMER CARE AND AFTERSALES
DCS2916
URGENT - DISTRIBUTE IMMEDIATELY**

Date: February 13, 2013

Subject: 12238D - Service Update
Loss of Battery Charge - Inspect Generator Control Module
Revised Part Information and Service Procedure Sections

Models: 2012-13 Buick LaCrosse and Regal; 2013 Chevrolet Malibu Eco
Equipped with eAssist

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager, and Warranty Administrator

The Part Information section has been updated to include additional part numbers, and the Service Procedure has been revised to clarify instructions. All technicians should review the revised service procedure immediately. Please discard all copies of bulletin 12238C.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12238D bulletin.pdf Acrobat PDF (201.1KB)
12238D bulletin

(
name:

t:

Phone: