



Internal notification for: G_0000171837 12313A - Special Coverage - Engine Balance Chain and Fuel Pump - Revised
gm_gmssg_q01

07/30/2013 01:27 PM

2 attachments



12313A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 7/30/2013

Ref. number: Service / Field Action / G_0000171837

Subject: 12313A - Special Coverage - Engine Balance Chain and Fuel Pump - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS3016
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 30, 2013

Subject: 12313A - Special Coverage Adjustment
Engine Balance Chain and Fuel Pump
Revised Part Information Section

Models: 2010-11 Buick LaCrosse, Chevrolet Equinox, GMC Terrain; 2011 Buick Regal Equipped with 2.4L Engine (LAF)

To: All Buick, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

The Part Information section in the attached bulletin has been revised. The quantity of the bolt, p/n 11588844, has been changed to 2 per vehicle. Please discard all copies of bulletin 12313.

END C; ..MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12313A bulletin.pdf Acrobat PDF (214.9KB)
12313A bulletin

(.....)
name:

Department:

Phone:

Intended General Manager, Parts & Service Director, Parts Manager, Service Advisor, Service roles: Manager, Used Vehicle Sales Manager, Warranty Administrator

Archives: 8/30/2013

Expires: 7/30/2014