
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Friday, September 06, 2013 3:55 PM
To:
Subject: Internal notification for: G_0000174366 13282 – Service Update Bulletin - Transmission Snap Ring Misalignment - Release From Stop Delivery
Attachments: 13282 Bulletin.pdf; 13282 VIN LIST.xlsx

Date: 9/06/2013

Ref. number: Service / Field Action / G_0000174366

Subject: **13282 – Service Update Bulletin - Transmission Snap Ring Misalignment - Release From Stop Delivery**

GM CUSTOMER CARE AND AFTERSALES
DCS3039
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 6, 2013

Subject: 13282 – Service Update Bulletin
Transmission Snap Ring Misalignment
Release From Stop Delivery

Models: 2013 Buick Regal, LaCrosse
2013 Chevrolet Malibu
Equipped with 6T40 Automatic Transmission (RPO MHH)

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

Vehicles involved in this service update were placed on stop delivery August 29, 2013. Completion of the service procedure contained in this bulletin will release the vehicle from stop delivery and allow a dealer to deliver the vehicle to a customer.

General Motors is announcing Service Update Bulletin 13282 today. The total number of U.S. vehicles involved is 27. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen will be updated in GWM on September 9, 2013. A list of the involved vehicles is also attached.

Service Update Bulletin (SUB) Information Link