

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Friday, October 04, 2013 11:54 AM  
**To:** ---  
**Subject:** Internal notification for: G\_0000176360 12313B - Special Coverage - Engine Balance Chain and Fuel Pump - Revised  
**Attachments:** 12313B bulletin.pdf

---

Date: 10/04/2013 Ref. number: Service / Field Action / G\_0000176360  
Subject: **12313B - Special Coverage - Engine Balance Chain and Fuel Pump - Revised**

---

GM CUSTOMER CARE AND AFTERSALES  
DCS3062  
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 4, 2013

Subject: 12313B – Special Coverage Adjustment  
Engine Balance Chain and Fuel Pump  
Revised Warranty Transaction Information

Models: 2010-11 Buick LaCrosse, Chevrolet Equinox, GMC Terrain; 2011  
Buick Regal Equipped with 2.4L Engine (LAF)

To: All Buick, Chevrolet, and GMC Dealers


Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

Bulletin 12313B has been revised to include a labor code for vehicles repaired that are still covered under warranty. Please discard all copies of bulletin 12313A.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

---

Message Attachment(s):

 12313B bulletin.pdf Acrobat PDF (218.5KB)  
12313B bulletin

---

Contact name: E-Mail:  
Department: Phone:  
Intended roles: General Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Used Vehicle Sales Manager, Warranty Administrator