



Internal notification for: G_0000170712 13013B - Service Update - Turbo-to-Exhaust Manifold Joint May Relax - Revised

gm_gmssg_q01 t c 1

07/12/2013 12:09 PM

2 attachments



13013B bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 7/12/2013 Ref. number: Service / Field Action / G_0000170712
Subject: 13013B - Service Update - Turbo-to-Exhaust Manifold Joint May Relax - Revised


**GM CUSTOMER CARE AND AFTERSALES
DCS3004
URGENT - DISTRIBUTE IMMEDIATELY**

Date: July 12, 2013
Subject: 13013B - Service Update
Turbo-to-Exhaust Manifold Joint May Relax
Revised Service Procedure
Models: 2013 Cadillac ATS and Chevrolet Malibu Equipped with 2.0L
Engine (LTG)
To: All Cadillac and Chevrolet Dealers
Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The service procedure in bulletin 13013B has been revised to add information about fastener/bolt extraction, if required. Please discard all copies of bulletin 13013A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

 13013B bulletin.pdf Acrobat PDF (343.7KB)
13013B bulletin

(
name:
Department: Phone:
Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,
roles: Service Advisor, Service Manager, Warranty Administrator
Archives: 8/12/2013 Expires: 7/12/2014