



Internal notification for: G_0000168191 13128B - Service Update - Software Enhancement Update - Revised

gm_gmssg_q01

06/14/2013 09:56 AM

2 attachments



13128B bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 6/14/2013

Ref. number: Service / Field Action / G_0000168191

Subject: 13128B - Service Update - Software Enhancement Update - Revised

GM CUSTOMER CARE AND AFTERSALES

DCS2984

URGENT - DISTRIBUTE IMMEDIATELY

Date: June 14, 2013

Subject: 13128B - Service Update
Software Enhancement Update
Revised Service Procedure

Models: 2013 Chevrolet Sonic, Spark, Trax Equipped with MyLink Radio (UF7)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The service procedure in bulletin 13128B has been revised. The sequence in which the programming events have to be performed has been updated. Please discard all copies of bulletin 13128A.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13128B bulletin.pdf Acrobat PDF (398.6KB)

13128B bulletin

name:

Department:

Phone:

Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,
roles: Service Advisor, Service Manager, Warranty Administrator

Archives: 7/14/2013

Expires: 6/14/2014