



**Internal notification for: G\_0000172550 13136B - Safety Recall - Loss of Battery Charge - Inspect Generator Control Module - Revised**  
gm\_gmssg\_q01 t n

08/08/2013 11:35 AM

2 attachments



13136B bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

---

Date: 8/08/2013 Ref. number: Service / Field Action / G\_0000172550  
Subject: 13136B - Safety Recall - Loss of Battery Charge - Inspect Generator Control Module - Revised

---

GM CUSTOMER CARE AND AFTERSALES  
DCS3026  
URGENT - DISTRIBUTE IMMEDIATELY


Date: August 8, 2013  
Subject: 13136B - Safety Recall  
Loss of Battery Charge - Inspect Generator Control Module  
Revised Service Procedure  
Models: 2012-13 Buick LaCrosse and Regal, 2013 Chevrolet Malibu ECO  
Equipped with eAssist  
To: All Buick and Chevrolet Dealers  
Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
Used Vehicle Sales Manager, and Warranty Administrator

The service procedure in bulletin 13136B has been revised. Step 2 has been expanded and Step 15 has been added. Please discard all copies of bulletin 13136A.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

---

Message Attachment(s):

 13136B bulletin.pdf Acrobat PDF (352.7KB)  
13136B bulletin

---

name:

Department: Service - Brand Quality

Phone:

Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,  
roles: Service Advisor, Service Manager, Used Vehicle Sales Manager, Warranty Administrator