



**Internal notification for: G\_0000172766 13142B - Safety Recall - Loss of Battery Charge - Replace Generator Control Module - Revised gm\_gmssg\_q01**

08/12/2013 02:36 PM

2 attachments



13142B bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 8/12/2013

Ref. number: Service / Field Action / G\_0000172766

Subject: 13142B - Safety Recall - Loss of Battery Charge - Replace Generator Control Module - Revised

**GM CUSTOMER CARE AND AFTERSALES  
DCS3029  
URGENT - DISTRIBUTE IMMEDIATELY**

Date: August 12, 2013

Subject: 13142B - Safety Recall  
Loss of Battery Charge - Replace Generator Control Module  
Revised Part Inspection

Models: 2012-13 Buick LaCrosse, Regal; 2013 Chevrolet Malibu ECO  
Equipped with eAssist

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
Used Vehicle Sales Manager, and Warranty Administrator

The part inspection procedure in bulletin 13142B has been revised. Please discard all copies of bulletin 13142A.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13142B bulletin.pdf Acrobat PDF (424.4KB)  
13142B bulletin

name:	E-M
Department: Service - Brand Quality	Phone:
Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,	
roles: Service Advisor, Service Manager, Used Vehicle Sales Manager, Warranty Administrator	
Archives: 9/12/2013	Expires: 8/12/2014