



**Internal notification for: G\_0000172761 13136C - Safety Recall - Loss of Battery Charge - Inspect Generator Control Module - Revised**  
gm\_gmssg\_q01

08/12/2013 01:32 PM

2 attachments



13136C bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

---

Date: 8/12/2013                      Ref. number: Service / Field Action / G\_0000172761  
Subject: 13136C - Safety Recall - Loss of Battery Charge - Inspect Generator Control Module - Revised

---

GM CUSTOMER CARE AND AFTERSALES  
DCS3028  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 12, 2013  
Subject: 13136C - Safety Recall  
Loss of Battery Charge - Inspect Generator Control Module  
Revised Part Inspection  
Models: 2012-13 Buick LaCrosse and Regal, 2013 Chevrolet Malibu ECO  
Equipped with eAssist  
To: All Buick and Chevrolet Dealers  
Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
Used Vehicle Sales Manager, and Warranty Administrator

The part inspection procedure in bulletin 13136C has been revised. Please discard all copies of bulletin 13136B.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

---

Message Attachment(s):

13136C bulletin.pdf Acrobat PDF (517.6KB)  
13136C bulletin

---

name:  
Department: Service - Brand Quality                      Phone:  
Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,  
roles: Service Advisor, Service Manager, Used Vehicle Sales Manager, Warranty Administrator