



**Internal notification for: G_0000169081 13186 - Service Update - Incorrect
Battery Current Sensor on Negative Battery Cable Assembly**
gm_gmssg_q01

06/26/2013 05:51 AM

3 attachments



13186 bulletin.pdf



13186 Inventory VINs.xls



GM Style Sheet.css

Your email client does not support HTML messages

Date: 6/26/2013

Ref. number: Service / Field Action / G_0000169081

Subject: 13186 - Service Update - Incorrect Battery Current Sensor on Negative Battery Cable Assembly

GM CUSTOMER CARE AND AFTERSALES
DCS2991
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 26, 2013

Subject: 13186 - Service Update Bulletin
Incorrect Battery Current Sensor on Negative Battery Cable Assembly

Models: 2013 Cadillac Escalade, Escalade ESV; Chevrolet Tahoe, Suburban;
GMC Yukon, Yukon XL; 2013-14 Chevrolet Captiva, Captiva Sport;
2014 Chevrolet Silverado, GMC Sierra

To: All Cadillac, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

General Motors is announcing Service Update Bulletin 13186 today. The total number of U.S. vehicles involved is approximately 6,700. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated June 26, 2013. A list of involved vehicles in dealer inventory is attached to this message.

Service Update Bulletin (SUB) Information Link

The SUB Information Link in GlobalConnect will be updated in the near future.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13186 bulletin.pdf Acrobat PDF (204.8KB)

13186 bulletin

13186 Inventory VINs.xls MS Excel Worksheet 8.0-2003 (Windows) (338.5KB)