
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Friday, November 01, 2013 4:16 PM
To:
Subject: Internal notification for: G_0000178480 13296A - Safety Recall - Insufficient Weld on Front Fuel Tank Strap Bracket - Revised
Attachments: 13296A bulletin.pdf

Date: 11/01/2013

Ref. number: Service / Field Action / G_0000178480

Subject: **13296A - Safety Recall - Insufficient Weld on Front Fuel Tank Strap Bracket - Revised**

**GM CUSTOMER CARE AND AFTERSALES
DCS3085
URGENT - DISTRIBUTE IMMEDIATELY**

Date: November 1, 2013

Subject: 13296A – Safety Recall
Insufficient Weld on Front Fuel Tank Strap Bracket
Customer Letter Added

Models: 2013-14 Chevrolet Sonic

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, Used Vehicle Sales Manager, and Warranty Administrator

Bulletin 13296A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 13296.

Customer Letter Mailing

The customer letter mailing will begin on November 7, 2013.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

 13296A bulletin.pdf Acrobat PDF (867.5KB)

13296A bulletin

Department: Service - Brand Quality

Phone: