

Internal notification for: G_0000171937 13230B - Safety Recall - Passenger Airbag Inflator Weld May Fracture Upon Airbag Deployment - Revised

gm_gmssg_q01

07/31/2013 03:29 PM

2 attachments

人 13230B bulletin.pdf

GM Style Sheet.css

Your email client does not support HTML messages

Date: 7/31/2013 Ref. number: Service / Field Action / G_0000171937

Subject: 13230B - Safety Recall - Passenger Airbag Inflator Weld May Fracture Upon Airbag Deployment -

Revised

GM CUSTOMER CARE AND AFTERSALES DCS3019 URGENT - DISTRIBUTE IMMEDIATELY

Date:

July 31, 2013

Subject:

13230B - Safety Recall

Passenger Airbag Inflator Weld May Fracture Upon Airbag Deployment

Revised Service Procedure and Customer Letter Added

Models:

2014 Chevrolet Silverado and GMC Sierra Crew Cabs

To:

All Chevrolet and GMC Dealers

Attention:

General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager,

and Warranty Administrator

The inspection procedure in the service procedure has been revised to clarify the location of the green stripe/dot. A copy of the customer letter has also been added to the bulletin. Please discard all copies of bulletin 13230A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):		
213230B bulletin.pdf	Acrobat PDF	(225.3KB)
13230B bulletin		

name:

Department: \

Phone:

Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,

roles: Service Advisor, Service Manager, Warranty Administrator