

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Tuesday, September 10, 2013 11:24 AM  
**To:**  
**Subject:** Internal notification for: G\_0000174546 13282A – Service Update Bulletin - Transmission Snap Ring Misalignment - Revised Warranty Transaction Information  
**Attachments:** 13282A Bulletin.pdf

---

Date: 9/10/2013 Ref. number: Service / Field Action / G\_0000174546  
Subject: **13282A – Service Update Bulletin - Transmission Snap Ring Misalignment - Revised Warranty Transaction Information**

---

**GM CUSTOMER CARE AND AFTERSALES  
DCS3041  
URGENT - DISTRIBUTE IMMEDIATELY**

Date: September 10, 2013

Subject: 13282A – Service Update Bulletin  
Transmission Snap Ring Misalignment  
Revised Warranty Transaction Information

Models: 2013 Buick Regal, LaCrosse  
2013 Chevrolet Malibu  
Equipped with 6T40 Automatic Transmission (RPO MHH)

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

This bulletin has been revised to correct the transmission exchange allowance. Please discard all copies of bulletin 13282.

**END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES**

---

Message Attachment(s):

 [13282A Bulletin.pdf](#) Acrobat PDF (130.3KB)  
13282A Bulletin

---

Contact nam

E-Mail:

Department: Service - Brand Quality

Phone:

Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Warranty Administrator