

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Friday, September 20, 2013 5:16 PM  
**To:**  
**Subject:** Internal notification for: G\_0000175221 13290A – Service Update Bulletin - Bent Piston Oil Squirters - Part Information Section Updated  
**Attachments:** 13290A Bulletin.pdf

---

Date: 9/20/2013 Ref. number: Service / Field Action / G\_0000175221  
Subject: **13290A – Service Update Bulletin - Bent Piston Oil Squirters - Part Information Section Updated**

---

**GM CUSTOMER CARE AND AFTERSALES  
DCS3049  
URGENT - DISTRIBUTE IMMEDIATELY**

**Date:** September 20, 2013

**Subject:** 13290A – Service Update Bulletin  
Bent Piston Oil Squirters  
Part Information Section Updated

**Models:** 2014 Chevrolet Silverado  
2014 GMC Sierra  
Equipped with 5.3L V8 Engine (L83) or 4.3L V6 Engine (LV3)

**To:** All Chevrolet and GMC Dealers


**Attention:** General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

This bulletin has been revised to include GM Product Quality Center (PQC) information and additional engine oil part numbers. A copy of the new bulletin is attached. Please discard all copies of bulletin 13290.

**END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES**

---

Message Attachment(s):

 [13290A Bulletin.pdf](#) Acrobat PDF (143.4KB)  
13290A Bulletin

---

Contact nam

E-Mail: