

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Friday, November 01, 2013 4:16 PM  
**To:**  
**Subject:** Internal notification for: G\_0000178480 13296A - Safety Recall - Insufficient Weld on Front Fuel Tank Strap Bracket - Revised  
**Attachments:** 13296A bulletin.pdf

---

Date: 11/01/2013 Ref. number: Service / Field Action / G\_0000178480  
Subject: **13296A - Safety Recall - Insufficient Weld on Front Fuel Tank Strap Bracket - Revised**

---

GM CUSTOMER CARE AND AFTERSALES  
DCS3085  
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 1, 2013

Subject: 13296A – Safety Recall  
Insufficient Weld on Front Fuel Tank Strap Bracket  
Customer Letter Added

Models: 2013-14 Chevrolet Sonic

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, Used Vehicle Sales Manager, and Warranty Administrator

Bulletin 13296A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 13296.


**Customer Letter Mailing**

The customer letter mailing will begin on November 7, 2013.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

---

Message Attachment(s):

 13296A bulletin.pdf Acrobat PDF (867.5KB)  
13296A bulletin

---

Department: Service - Brand Quality

Phone: