
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Tuesday, October 01, 2013 2:52 PM
To:
Subject: Internal notification for: G_0000176029 13310A - Service Update - Inventory Vehicles Only - Seatback Movement - Revised
Attachments: 13310A bulletin.pdf

Date: 10/01/2013 Ref. number: Service / Field Action / G_0000176029
Subject: **13310A - Service Update - Inventory Vehicles Only - Seatback Movement - Revised**

**GM CUSTOMER CARE AND AFTERSALES
DCS3057
URGENT - DISTRIBUTE IMMEDIATELY**

Date: October 1, 2013

Subject: 13310A – Service Update for Inventory Vehicles Only
Seatback Movement
Revised Service Procedure

Models: 2014 Chevrolet Silverado and GMC Sierra 1500 Equipped with
Manual Reclining Seatback

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

Bulletin 13310A has been revised to include an inspection procedure. Please discard all copies of bulletin 13310.

**END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES**

Message Attachment(s):

 [13310A bulletin.pdf](#) Acrobat PDF (851.9KB)

Contact name:

E-Mail:

Department:

Phone:

Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Warranty Administrator

Archives: 11/01/2013

Expires: 10/01/2014