

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Monday, November 11, 2013 12:09 PM  
**To:**  
**Subject:** Internal notification for: G\_0000179075 13380A - Noncompliance Recall - HVAC Control Inoperable - Revised  
**Attachments:** 13380A bulletin.pdf

---

Date: 11/11/2013 Ref. number: Service / Field Action / G\_0000179075  
Subject: **13380A - Noncompliance Recall - HVAC Control Inoperable - Revised**

---

GM CUSTOMER CARE AND AFTERSALES  
DCS3094  
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 11, 2013

Subject: 13380A – Noncompliance Recall  
HVAC Control Inoperable  
Revised Service Procedure

Models: 2014 Chevrolet Malibu

To: All Chevrolet Dealers


Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

The service procedure in bulletin 13380A has been revised. Dealers do not need to perform the actuator recalibration function. Please discard all copies of bulletin 13380.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

---

Message Attachment(s):

 13380A bulletin.pdf Acrobat PDF (130.8KB)  
13380A bulletin

---

Department: Service - Brand Quality Phone:  
Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Warranty Administrator  
Archives: 12/11/2013 Expires: 11/11/2014