



GROUP  
Electrical

MODEL  
Sedona (VQ)  
2006-2012MY

NUMBER  
PS238

DATE  
January 2013



# TECHNICAL OPERATIONS

SUBJECT: AUDIBLE TONE FROM BACK-UP ASSIST ALWAYS ON

If you encounter a customer complaint relating to the audible tone from the back-up assist feature remaining on at all times, inspect the sensors in the rear bumper for possible collision damage causing a short in the sensor. Also, make sure to check the harnesses feeding the sensors for continuity to ground. Refer to the schematic diagram (A) below or to the Body Electrical section of the service manual for detailed repair information.

