



GROUP
Body

MODEL
2013MY
Sorento (XMa)

NUMBER
PS239

DATE
March 2013



TECHNICAL OPERATIONS

SUBJECT: RATTLE FROM THE RIGHT AND/OR LEFT SIDE OF DASHBOARD

Some customers may complain of a rattle type noise coming from the right and/or left side of the dash while driving at highway speeds. This concern may be caused by the fender trim rubbing against the fender liner. To resolve this concern, use a self-tapping screw to secure the fender trim and the fender liner, as shown. Test drive the vehicle and confirm the noise is no longer present.



PART REQUIRED:

Part Number	Description	Qty.
12431-03127B	T/SCREWG	1