



Internal notification for: G_0000155845 12106A - Safety Recall - Shift Lever Indicator May Not Display Correct Gear - Revised
gm_gmssg_q01

01/08/2013 02:46 PM

2 attachments



12106A bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/08/2013 Ref. number: Service / Field Action / G_0000155845
Subject: 12106A - Safety Recall - Shift Lever Indicator May Not Display Correct Gear - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2878
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 8, 2013

Subject: 12106A - Safety Recall
Shift Lever Indicator May Not Display Correct Gear
Revised Service Procedure and Warranty Transaction Information

Models: 2007-2010 Saturn AURA; 2008-2010 Chevrolet Malibu and Pontiac G6 Equipped with 4-Speed Automatic Transmission (ME7/MN5) and
2005-2008 Pontiac G6; 2007-2008 Saturn AURA Equipped with 4-Speed Automatic Transmission (ME7/MN5) and Were Serviced with a Suspect Replacement Shift Cable

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

The Service Procedure and Warranty Transaction Information sections in this bulletin have been revised to include and inspection of the transmission shift cables. Please discard all copies of bulletin 12106.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12106A bulletin.pdf Acrobat PDF (514.5KB)
12106A bulletin
