



**Internal notification for: G_0000155990 10282E - Safety Recall - Harsh
Transmission Shift, Engine May Not Start, MIL or SES Lamp - Revised**
gm_gmssg_q01

01/09/2013 02:13 PM

2 attachments



10282E bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/09/2013

Ref. number: Service / Field Action / G_0000155990

Subject 10282E - Safety Recall - Harsh Transmission Shift, Engine May Not Start, MIL or SES Lamp -
: Revised

GM CUSTOMER CARE AND AFTERSALES

DCS2879

URGENT - DISTRIBUTE IMMEDIATELY

Date: January 9, 2013

Subject: 10282E - Safety Recall
Harsh Transmission Shift, Engine Stall, Engine May Not Start, MIL
or Service Engine Soon Lamp
Revised Service Procedure

Models: 2005-2008 Pontiac Vibe 2-Wheel Drive Equipped with 1.8L MFI
Engine (LV6)

To: All GM Dealers


Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The Service Procedure section in bulletin 10282E has been revised to include the installation of the Recall Identification Label and the completion of a "Proof of Correction" certificate for all vehicles registered in California. The California Air Resources Board (CARB) requires recalls that involve emission related parts be completed prior to California registration renewal. Uncorrected recalls will result in the inability of the customer to renew their California vehicle registration. Please discard all copies of bulletin 10282D.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

 10282E bulletin.pdf Acrobat PDF (258.6KB)

10282E bulletin