



Internal notification for: G_0000156973 13008A - Safety Recall - Rear
Suspension Bolts May Not Be To Proper Torque Specification - Revised
gm_gmssg_q01

01/22/2013 11:18 AM

3 attachments



13008A bulletin.pdf



13008 Dealer list.xls



GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/22/2013

Ref. number: Service / Field Action / G_0000156973

Subject 13008A - Safety Recall - Rear Suspension Bolts May Not Be To Proper Torque Specification -
: Revised

GM CUSTOMER CARE AND AFTERSALES

DCS2887

URGENT - DISTRIBUTE IMMEDIATELY

Date: January 22, 2013

Subject: 13008A - Safety Recall
Rear Suspension Bolts May Not Be To Proper Torque Specification
Revised Part Numbers in Part Information Section and Service Procedure

Models: 2013 Chevrolet Malibu

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

Part numbers for the rear stab bar shaft link bolt, rear suspension link inner nut, and rear suspension lower control arm inner nut, have been revised in the Part Information section, and in the Static Torque Specification Table and Fastener Replacement Torque Specification Table.

As a reminder, all involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in the bulletin has been performed on the vehicle.

A list of involved vehicles is attached to this message.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):



13008A bulletin.pdf Acrobat PDF (554.5KB)

13008A bulletin