



Internal notification for: G_0000157271 12292A - Emission Recall - Knock Sensor Wiring Harness Connection Reversed - Revised
gm_gmssg_q01 t

01/24/2013 11:20 AM

2 attachments



12292A bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/24/2013 Ref. number: Service / Field Action / G_0000157271
Subject: 12292A - Emission Recall - Knock Sensor Wiring Harness Connection Reversed - Revised

**GM CUSTOMER CARE AND AFTERSALES
DCS2888
URGENT - DISTRIBUTE IMMEDIATELY**

Date: January 24, 2013
Subject: 12292A - Emission Recall
Knock Sensor Wiring Harness Connection Reversed
Revised Part Information and Service Procedure Sections
Models: 2013 Chevrolet Malibu Equipped with 2.5L Engine (LCV)
To: All Chevrolet Dealers
Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

Bulletin 12292A has been revised to provide the part number for the rear transmission mount bolts, which require replacement. The service procedure has also been updated. Please discard all copies of bulletin 12292.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12292A bulletin.pdf Acrobat PDF (384.6KB)
12292A bulletin

De,

t:

Phone:

Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,