



Internal notification for: G_0000157291 13013 - Service Update - Turbo-to-Exhaust Manifold Joint May Relax gm_gmmsg_q01

01/24/2013 03:35 PM

3 attachments



13013 bulletin.pdf



13013 Inventory VINs.xls



GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/24/2013 Ref. number: Service / Field Action / G_0000157291
Subject: 13013 - Service Update - Turbo-to-Exhaust Manifold Joint May Relax

**GM CUSTOMER CARE AND AFTERSALES
DCS2889
URGENT - DISTRIBUTE IMMEDIATELY**

Date: January 24, 2013
Subject: 13013 - Service Update Bulletin
Turbo-to-Exhaust Manifold Joint May Relax
Models: 2013 Cadillac ATS and Chevrolet Malibu Equipped with 2.0L Engine (LTG)
To: All Cadillac and Chevrolet Dealers
Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Service Update Bulletin 13013 today. The total number of U.S. vehicles involved is approximately 14,500. Please see the attached bulletin for details.

Global Warranty Management (GWM)
The "Investigate Vehicle History" (IVH) screen will be updated January 25, 2013. A list of involved vehicles in dealer inventory is attached to this message.

Service Update Bulletin (SUB) Information Link
The SUB Information Link in GlobalConnect will be updated in the near future.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13013 bulletin.pdf Acrobat PDF (343.0KB)
13013 bulletin

13013 Inventory VINs.xls Microsoft Office Excel Worksheet 8.0-2003 (Windows) (740.5KB)
13013 Inventory VINs
