



Internal notification for: G_0000157297 12106B - Safety Recall - Shift Lever Indicator May Not Display Correct Gear - Revised
gm_gmssg_q01

01/24/2013 02:35 PM

2 attachments



12106B bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/24/2013

Ref. number: Service / Field Action / G_0000157297

Subject: 12106B - Safety Recall - Shift Lever Indicator May Not Display Correct Gear - Revised

**GM CUSTOMER CARE AND AFTERSALES
DCS2890
URGENT - DISTRIBUTE IMMEDIATELY**

Date: January 24, 2013

Subject: 12106B - Safety Recall
Shift Lever Indicator May Not Display Correct Gear
Revised Service Procedure

Models: 2008-10 Chevrolet Malibu, Pontiac G6; 2007-10 Saturn AURA
Equipped with 4-Speed Automatic Transmission (ME7/MN5)
And
2005-08 Pontiac G6; 2007-08 Saturn AURA Equipped with 4-Speed
Automatic Transmission (ME7/MN5) and Serviced with a Suspect
Replacement Shift Cable

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The service procedure has been revised to include an inspection to determine if the clam shell has been installed on the transmission shift cable. Please discard all copies of bulletin 12106A.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12106B bulletin.pdf Acrobat PDF (515.3KB)

12106B bulletin