



**Internal notification for: G_0000157403 13008A - Safety Recall - Rear
Suspension Bolts May Not Be To Proper Torque Specification - EXPANDED
POPULATION
gm_gmssg_q01**

01/25/2013 06:20 PM

2 attachments



13008A Additional Involved VINS.xls GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/25/2013

Ref. number: Service / Field Action / G_0000157403

Subje 13008A - Safety Recall - Rear Suspension Bolts May Not Be To Proper Torque Specification -
ct: EXPANDED POPULATION

**GM CUSTOMER CARE AND AFTERSALES
DCS2892
URGENT - DISTRIBUTE IMMEDIATELY**

Date: January 25, 2013

Subject: 13008A - Safety Recall - Population Expanded
Rear Suspension Bolts May Not Be To Proper Torque Specification
Additional Vehicles Added to Population

Models: 2013 Chevrolet Malibu

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The population for this safety recall has been expanded. The additional involved vehicles are included in the attached VIN list.

As a reminder, all involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in the bulletin has been performed on the vehicle.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13008A Additional Involved VINS.xls Microsoft Office Excel Worksheet 8.0-2003 (Windows) (700KB)
13008A - ADDITIONAL INVOLVED VINS