

Internal notification for: G_0000157480 13003 - Service Update - Inventory Vehicles Only - Automatic Radio Volume Increase and/or Radio Control Assembly Buttons Not Operating as Designed gm_gmssg_g01 01/31/2013 05:

01/31/2013 05:35 AM

| - 3 | attachments |
|-----|---|
| | and the second se |

13003 bulletin.pdf 13003 Involved VINs.xls GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/31/2013

Ref. number: Service / Field Action / G_0000157480

Subje 13003 - Service Update - Inventory Vehicles Only - Automatic Radio Volume Increase and/or Radio ct: Control Assembly Buttons Not Operating as Designed

GM CUSTOMER CARE AND AFTERSALES DCS2894 URGENT - DISTRIBUTE IMMEDIATELY

Date: January 31, 2013

Subject: 13003 - Service Update Bulletin - Inventory Vehicles Only Automatic Radio Volume Increase and/or Radio Control Assembly Buttons Not Operating as Designed

Models: 2013 Cadillac ATS, SRX, XTS

To: All Cadillac Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Service Update Bulletin 13003 today. The total number of U.S. vehicles involved is approximately 8,900. Please see the attached bulletin for details.

Global Warranty Management (GWM) The "Investigate Vehicle History" (IVH) screen will be updated January 31, 2013. A list of involved vehicles is attached to this message.

Service Update Bulletin (SUB) Information Link The SUB Information Link in GlobalConnect will be updated in the near future.

END OF MESSAGE GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s): 13003 bulletin.pdf Acrobat PDF (437.4KB) 13003 bulletin