



**Internal notification for: G\_0000163982 13077A - Service Update -  
Transmission Fluid Leak - Revised  
gm\_gmssg\_q01**

04/15/2013 08:50 AM

2 attachments



13077A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 04/15/2013      Ref. number: Service / Field Action / G\_0000163982  
Subject: 13077A - Service Update - Transmission Fluid Leak - Revised

**GM CUSTOMER CARE AND AFTERSALES  
DCS2943  
URGENT - DISTRIBUTE IMMEDIATELY**

Date: April 15, 2013

Subject: 13077A - Service Update  
Transmission Fluid Leak  
Revised Part Information, Service Procedure, and Warranty  
Transaction Information Sections

Models: 2013 Cadillac SRX Equipped with 6-Speed Automatic Transmission (6T70)

To: All Cadillac Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
and Warranty Administrator

The inspection procedure in bulletin 13077A has been revised, transmission fluid has been added to the parts section, and a labor code for the transmission replacement, if necessary, has been added. Please discard all copies of bulletin 13077.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

13077A bulletin.pdf Acrobat PDF (280.2KB)  
13077A bulletin

Contact name: E-Mail

Department: Phone:

Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager,