

Symptom: Low power and MIL on with DTC - P0087 (Fuel Rail/System Pressure - Too Low)

Repair: Recommend replacement of high pressure fuel pump and metal fuel line. Then clear code and test drive. This should correct the concern.

Note: Tech Tips are not a substitute for proper diagnosis.