



TECH TIP: Rattle Noise From Dash

NUMBER: TT019

MODEL: 2011 Sportage (SL)

DATE: 11/15/2013

Symptom: Rattle noise from dash at speeds above 50 mph.

Repair: Refer to Pitstop PS209r1 for procedure to correct this concern.

Note: Tech Tips are not a substitute for proper diagnosis.