



TECH TIP: ESC DTC C1201 – C1211

NUMBER: TT026

MODEL: 2012 Sedona (VQ)

DATE: 11/15/2013

Symptom: ESC DTC C1201 – C1211

Repair: Check the wheel speed sensor tone wheel that the DTC is associated with and see if it has separated from or slipped on the hub. If the tone wheel has separated from the hub, the hub assembly will need be replaced to correct the DTC.

Note: Tech Tips are not a substitute for proper diagnosis.