



**Internal notification for: G\_0000164892 12106C - Safety Recall Revision -  
Shift Lever Indicator May Not Display Correct Gear  
gm\_gmssg\_q01**

05/01/2013 01:57 PM

2 attachments



12106C Bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 5/01/2013

Ref. number: Service / Field Action / G\_0000164892

Subject: 12106C - Safety Recall Revision - Shift Lever Indicator May Not Display Correct Gear

**GM CUSTOMER CARE AND AFTERSALES  
DCS2956  
URGENT - DISTRIBUTE IMMEDIATELY**

Date:	May 1, 2013
Subject:	12106C - Safety Recall Revision Shift Lever Indicator May Not Display Correct Gear
Models:	2008-2010 Chevrolet Malibu 2008-2010 Pontiac G6 2007-2010 Saturn AURA Equipped with 4-Speed Automatic Transmission (ME7/MN5) and 2005-2008 Pontiac G6 2007-2008 Saturn AURA Equipped with 4-Speed Automatic Transmission (ME7/MN5) and Serviced with a Suspect Replacement Shift Cable
To:	All GM Dealers
Attention:	General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

Safety Recall 12106B is being revised. The suspect transmission shift cables involved in this recall were also sold to customers as service replacement parts. Our records indicate that a small number of vehicles were repaired by GM dealers with suspect cables sold as service replacement parts. These vehicles were not included in the original recall and have been added to the involved vehicle population. They require completion of the service procedure described in this bulletin.

Additional vehicles may have been repaired with suspect cables sold as service replacement parts but VIN information is not available. Included in this bulletin is a "Safety Recall Notice" for public display at your