



Subject

**Steering Intermediate Shaft Noise**

Market

USA

Service Category

Steering

Section

Steering Gear/Linkage

Applicability

2009-2013 LS 460, 2008-2013 LS600H

**APPLICABLE VEHICLES**

2008-2013	LS600H	2009-2013	LS460
-----------	--------	-----------	-------

**CONDITION**

While turning the steering wheel, a slight binding, rubbing or pop noise is heard from the steering column or intermediate shaft.

**RECOMMENDATIONS**

This issue is currently under investigation.

Please contact Technical Assistance (TAS) to submit details on vehicles identified matching the condition described above prior to repair.

If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

**LINK REFERENCES**

This Tech Tip does not contain any link references.