

NUMBER: 07-002-13

GROUP: Cooling

DATE: July 30, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-055. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Coolant Weepage At EGR Hose

OVERVIEW:

This bulletin involves replacing the EGR hose.

MODELS:

2012 - 2013

LX

Chrysler 300 (International Only)

NOTE: This bulletin applies to vehicles with the 3.0L V6 Turbo Diesel Engine (sales code EXF) built on or before June 03, 2013 (MDH 0603XX)

SYMPTOM/CONDITION:

The EGR hose may weep coolant.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
(1)	68233187AA	EGR Coolant Hose

REPAIR PROCEDURE:

1. Drain the cooling system. Follow the detailed procedures available in DealerCONNECT/TECHCONNECT, Refer To 07 - Cooling - Standard Procedure.
2. Lower the belly pan splash shield.
3. Lower the rear transmission splash shield.
4. Replace the EGR coolant hose.




Fig. 1 EGR

1 - EGR Coolant Hose

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
25- 01- 47- 90	Hose, EGR Cooler Replace (2- Skilled)	10- Diesel	.07 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------