

**Tech Tip** T-TT-0221-13

February 14, 2013

USA

Capacitive Sensor Sensitivity Setting for Navigation System (Navigation Receiver Type/Radio and Display Type) and Air Conditioning System

Service Category

Audio/Visual/Telematics

Navigation/Multi Info Display

2013 Avalon/ Avalon HV

## **APPLICABLE VEHICLES**

2013 Avalon 2013 Avalon HV

## CONDITION

Some customers may feel sensitivity of control buttons of Navigation system and air conditioning system is low (unresponsive) or high (responds before touching the sensor).

**Note:** Tech Tip is issued for your convenience due to the potential difficulty of finding this information in repair manual.

## RECOMMENDATIONS

Please see the attached links from the repair manual for details on how to adjust sensitivity setting.

## LINK REFERENCES

- NAVIGATION / MULTI INFO DISPLAY: NAVIGATION SYSTEM (for Navigation Receiver Type): OPERATION CHECK; 2013 MY Avalon [10/2012 -]
- NAVIGATION / MULTI INFO DISPLAY: NAVIGATION SYSTEM (for Radio and Display Type): OPERATION CHECK; 2013 MY Avalon [10/2012 -]
- HEATING / AIR CONDITIONING: AIR CONDITIONING SYSTEM: SYSTEM DESCRIPTION;
  2013 MY Avalon [10/2012 -]

Expires on

05/14/2013

© 2013, Toyota Motor Sales, USA

Page 1 of 1

Ver. 2.1 8/28/2011 T