



**NUMBER:** 08-010-13

**GROUP:** Electrical

**DATE:** February 28, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

**SUBJECT:**

Fluid Leak From Washer Reservoir (X44 Warranty Extension 5 Years/100,000 Miles (160,000 KMS))

**OVERVIEW:**

This bulletin involves inspecting and/or replacing the washer reservoir.

**MODELS:**

|           |      |                                |
|-----------|------|--------------------------------|
| 2010-2011 | (DJ) | Ram 2500 Pickup                |
| 2011      | (DD) | Ram 3500 Cab Chassis           |
| 2011      | (DP) | Ram 4500-5500 Cab Chassis      |
| 2010-2011 | (DX) | Dodge Reg Cab Chassis (Mexico) |
| 2010-2011 | (D2) | Ram 3500 Pickup                |

**NOTE:** This bulletin applies vehicles built before March 30, 2012 (MDH 0330XX) equipped with a Diesel engine (sales code ETJ).

**SYMPTOM/CONDITION:**

A customer may have a condition where fluid is leaking from the washer reservoir. On further inspection the technician may find cracks in the reservoir by the washer pump pocket.

**NOTE:** Always check VIP to verify if a vehicle is involved in a warranty extension. A vehicle involved in this Warranty Extension will display an (X44) Washer Reservoir leak message in VIP.

**DIAGNOSIS:**

If the customer describes the symptom, perform the Repair Procedure.

**PARTS REQUIRED:**

| Qty. | Part No.   | Description               |
|------|------------|---------------------------|
| 1    | 05182304AF | Washer Reservoir Assembly |

**REPAIR PROCEDURE:**

1. Inspect for cracks in the washer reservoir, near the washer pump area. If cracks are found replace the reservoir assembly.
2. Replace the Washer Reservoir assembly following TechCONNECT> Group 08 - Electrical> 8R - Windshield Washer> Reservoir, Windshield Washer> Removal/Installation> Diesel Engine.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

**NOTE:** Vehicles included in this Service Bulletin have a 5 Years/100,000 Miles (160,000 KMS) coverage warranty for this repair. See Warranty Bulletins; U.S. D-13-13, Canada SAB-2013-07 or International ID-13-07 for details associated with the extended warranty.

| Labor Operation No: | Description                           | Amount   |
|---------------------|---------------------------------------|----------|
| 23-43-05-90         | Reservoir, Replace (0 - Introduction) | 0.5 Hrs. |

**FAILURE CODE:**

|    |                |
|----|----------------|
| ZZ | Service Action |
|----|----------------|