



Connection offline

Vehicle-specific service

Topic	Over check for clip removal cars having had E788 applied between 25th July and 16th August 2013
Market area	Worldwide Bentley (1WBE)
Brand	Bentley
Transaction No.	2035067/1
Level	EH
Status	Approval
Release date	

Vehicle data

GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
394*	2012	E		*	*	*
394*	2013	E		*	*	*
3W4*	2011	E		*	*	*
3W7*	2011	E		*	*	*
3W7*	2012	E		*	*	*
3W7*	2013	E		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	DF2	3W	1	A	C				
SCB	DE2	3W	9	A	C				
SCB	DR3	ZA	3	B	C				
SCB	DR3	ZA	5	B	C				
SCB	DH2	3W	4	B	C				
SCB	DH2	3W	3	B	C				
SCB	DH2	3W	1	B	C				
SCB	DJ2	3W	2	B	C	0			
SCB	DP3	ZA	X	B	C				
SCB	DG2	3W	2	B	C				
SCB	DP3	ZA	8	B	C				
SCB	DK2	3W	7	B	C				
SCB	DR3	ZA	3	B	C				
SCB	DP3	ZA	0	B	C				

SCB	DK0	3W	7	B	C			
SCB	DU3	ZA	9	B	C			
SCB	DR3	ZA	9	B	C			
SCB	DH2	3W	X	B	C			
SCB	DR3	ZA	0	B	C			
SCB	DU3	ZA	4	B	C			
SCB	DR3	ZA	6	B	C			
SCB	DU3	ZA	3	B	C			
SCB	DH2	3W	7	B	C			
SCB	DU3	ZA	3	B	C			
SCB	DK2	3W	9	B	C			
SCB	DR3	ZA	9	B	C			
SCB	DU3	ZA	4	B	C			
SCB	DU3	ZA	6	B	C			
SCB	DJ2	3W	8	B	C			
SCB	DF2	3W	5	B	C			
SCB	DJ2	3W	6	B	C			
SCB	DR3	ZA	6	B	C			
SCB	DH2	3W	1	B	C			
SCB	DH2	3W	5	B	C			
SCB	DP3	ZA	9	B	C			
SCB	DK2	3W	4	B	C			
SCB	DH2	3W	2	B	C			
SCB	DJ2	3W	8	B	C			
SCB	DH2	3W	1	B	C			
SCB	DK2	3W	X	C	C			
SCB	DU3	ZA	3	C	C			
SCB	DU3	ZA	8	C	C			
SCB	GH2	3W	X	C	C			
SCB	GH2	3W	1	C	C			
SCB	DK2	3W	5	C	C			
SCB	GR3	ZA	2	C	C			
SCB	GR3	ZA	7	C	C			
SCB	GR3	ZA	0	C	C			
SCB	GH2	3W	7	C	C			
SCB	GH2	3W	7	C	C			
SCB	GH2	3W	4	C	C			
SCB	GH2	3W	4	C	C			
SCB	GR3	ZA	2	C	C			
SCB	GR3	ZA	0	C	C			
SCB	GH2	3W	1	C	C			
SCB	GR3	ZA	8	C	C			

SCB	GR3	ZA	3	C	C			
SCB	GR3	ZA	6	C	C			
SCB	GH2	3W	0	C	C			
SCB	GR3	ZA	2	C	C			
SCB	GR3	ZA	7	C	C			
SCB	GR3	ZA	7	C	C			
SCB	GR3	ZA	3	C	C			
SCB	GR3	ZA	2	C	C			
SCB	GR3	ZA	6	C	C			
SCB	GH2	3W	2	C	C			
SCB	GR3	ZA	1	C	C			
SCB	GR3	ZA	4	C	C			
SCB	GH2	3W	1	C	C			
SCB	GH2	3W	5	C	C			
SCB	GH2	3W	0	C	C			
SCB	GH2	3W	1	C	C			
SCB	GH2	3W	1	C	C			
SCB	GR3	ZA	7	C	C			
SCB	GR3	ZA	3	C	C			
SCB	GR3	ZA	3	C	C			
SCB	GH2	3W	7	D	C			
SCB	GR3	ZA	6	D	C			
SCB	GR3	ZA	3	D	C			
SCB	GH2	3W	8	D	C			
SCB	GR3	ZA	1	D	C			
SCB	GE2	3W	5	D	C			
SCB	GE2	3W	7	D	C			
SCB	GR3	ZA	8	D	C			
SCB	GR3	ZA	5	D	C			
SCB	GR3	ZA	6	D	C			
SCB	GH2	3W	8	D	C			
SCB	GJ2	3W	4	D	C			
SCB	GR3	ZA	1	D	C			
SCB	GR3	ZA	9	D	C			
SCB	GJ2	3W	X	D	C			
SCB	GR3	ZA	6	D	C			
SCB	GH2	3W	1	D	C			
SCB	GJ2	3W	5	D	C			
SCB	GR3	ZA	5	D	C			
SCB	GR3	ZA	9	D	C			
SCB	GJ2	3W	0	D	C			
SCB	GJ2	3W	6	D	C			

SCB	GR3	ZA	2	D	C			
SCB	GJ2	3W	7	D	C			
SCB	GR3	ZA	5	D	C			
SCB	GR3	ZA	6	D	C			
SCB	GR3	ZA	X	D	C			
SCB	GJ2	3W	6	D	C			
SCB	GR3	ZA	8	D	C			
SCB	GT3	ZA	1	D	C			
SCB	GJ2	3W	6	D	C			
SCB	GH2	3W	0	D	C			
SCB	GJ2	3W	7	D	C			
SCB	GR3	ZA	X	D	C			
SCB	GJ2	3W	6	D	C			
SCB	GT3	ZA	7	D	C			
SCB	GJ2	3W	X	D	C			
SCB	GH2	3W	3	D	C			
SCB	GH2	3W	4	D	C			
SCB	GJ2	3W	4	D	C			
SCB	GR3	ZA	5	D	C			
SCB	GJ2	3W	5	D	C			
SCB	GH2	3W	8	D	C			
SCB	GJ2	3W	6	D	C			
SCB	GJ2	3W	3	D	C			
SCB	GJ2	3W	9	D	C			
SCB	GE2	3W	8	D	C			
SCB	GT3	ZA	2	D	C			
SCB	GJ2	3W	1	D	C			
SCB	GT3	ZA	5	D	C			
SCB	GJ2	3W	7	D	C			
SCB	GT3	ZA	5	D	C			
SCB	GJ2	3W	3	D	C			
SCB	GT3	ZA	0	D	C			
SCB	GT3	ZA	7	D	C			
SCB	GJ2	3W	5	D	C			
SCB	GT3	ZA	9	D	C			
SCB	GU3	ZA	6	D	C			
SCB	GU3	ZA	1	D	C			
SCB	GT3	ZA	1	D	C			
SCB	GT3	ZA	1	D	C			
SCB	GT3	ZA	0	D	C			
SCB	GK2	3W	3	D	C			
SCB	GT3	ZA	2	D	C			

SCB	GN2	3W	7	D	C			
SCB	GK2	3W	X	D	C			
SCB	GN2	3W	6	D	C			
SCB	GT3	ZA	1	D	C			
SCB	GK2	3W	0	D	C			
SCB	GT3	ZA	1	D	C			
SCB	GT3	ZA	1	D	C			
SCB	GT3	ZA	7	D	C			
SCB	GT3	ZA	5	D	C			
SCB	GT3	ZA	7	D	C			
SCB	GN2	3W	2	D	C			
SCB	GT3	ZA	5	D	C			
SCB	GT3	ZA	X	D	C			
SCB	GU3	ZA	5	D	C			
SCB	DR3	ZA	8	B	C			
SCB	DE2	3W	6	A	C			
SCB	DF2	3W	0	A	C			
SCB	DF2	3W	0	A	C			
SCB	DE2	3W	6	A	C			
SCB	DE2	3W	2	A	C			
SCB	DE2	3W	4	A	C			
SCB	DK0	3W	3	B	C			
SCB	DF2	3W	0	A	C	0		

Documents

Document name
master.xml
master.doc



Connection offline

Vehicle-specific service

Transaction No.: 2035067/1

Over check for clip removal cars having had E788 applied between 25th July and 16th August 2013


Customer statement / workshop findings**Technical background**

Due to an omission in the text of campaign document E788, *Convertible roof – revised clip arrangement – C flap Bowden cable (SC13/12) version 1*, one clip on each Bowden cable (two clips in total) that should have been deleted may still be present. Each specific VIN requiring this over check is listed in this document

Therefore at the next scheduled dealer visits check for the presence and if necessary remove the two relevant clips (D) detailed below. Version two of campaign document E788, published on the 16th August 2013, incorporates the detail for removal of these clips

This over check is only applicable to cars that had E788 applied using version 1 published between 25th July 2013 and 16th August 2013.

Note cars that had both E788 and TPI 2033467/1 applied, that is cars that have the longer cross over C flap Bowden cable fitted, are not affected.

Production change**Measure**

Temporarily reposition the corner of the hood stowage compartment carpet to view point D, if present discard the clip securing the Bowden cable at point D perform this operation on both sides of the car. Reposition the corner of the hood stowage compartment carpet.

Warranty accounting instructions

Warranty Type 110 or 910

Labour Operation Code 61 91 10 99 (for RO open date on or before 19 September 2013)

61 91 10 00 (for RO open date after 19 September 2013)

Damage Service Number 61 43

Damage Service Code 01 00

Damage Location 003

Time 10 TU