



Service Bulletin

File in Section: -

Bulletin No.: PIP5143B

Date: September, 2013

PRELIMINARY INFORMATION

Subject: Lifter Noise Or SES Light With A P0300 Set

Models: 2014 Chevrolet Silverado 1500
2014 GMC Sierra 1500
Built with RPO's 5.3L L83

This PI was superseded to update the labor operation. Please discard PIP5143A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The customer may experience a lifter noise or SES light with a P0300 set.

If the vehicle was built before 7/8/2013 the following should be performed.

Recommendation/Instructions

After repairing an engine with a collapsed intake lifter on an AFM cylinder, check TIS to web for any applicable ECM calibrations.

This would be for vehicle built before July 8, 2013.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.