



Service Bulletin

File in Section: -

Bulletin No.: PIP5143

Date: August, 2013

PRELIMINARY INFORMATION

Subject: Lifter Noise Or SES Light With A P0300 Set

Models: 2014 Chevrolet Silverado 1500
2014 GMC Sierra 1500
Built with RPO's 5.3L L83

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The customer may experience a lifter noise or SES light with a P0300 set.

Complete the following recommendation if the vehicle was built before July 8th, 2013.

Recommendation/Instructions

Search TIS2WEB and complete the applicable service calibration update when repairing an engine with a concern of a collapsed intake lifter on trucks built prior to July 8th, 2013.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.