



Service Bulletin

File in Section: -

Bulletin No.: PIP5058B

Date: July, 2013

PRELIMINARY INFORMATION

Subject: 2013 Chevrolet Spark AISIN Transmission Torque Converter Valve Body And TCM Restriction Has Ended

Models: 2013 Chevrolet Spark
with AISIN (MNG) 80-40LE Transmission

This PI was superseded to end the PQC restriction. Please discard PIP5058A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

As part of our ongoing quality improvement efforts, the PQC (Product Quality Center) restriction on P/N 25181682, 25188088, 25188306, 25181372 (2013 Chevrolet Spark AISIN transmission) has now ended.

Recommendation/Instructions

General Motors Engineering would like to thank the dealers that participated in the Chevrolet Spark AISIN transmission restriction.

Dealers can now order the above parts numbers through their parts department. Calls to the PQC are no longer necessary.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.