



Service Bulletin

File in Section: -

Bulletin No.: PIE0264

Date: August, 2013

PRELIMINARY INFORMATION

Subject: Engineering Information – Rattle Type Noise at Engine Start-Up

Models: 2012-2013 Chevrolet Cruze
Equipped with 1.8L Engine (RPO LUW or LWE)
and Manual Transmission

Attention: Proceed with this PI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information PIs.

Condition

Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.

Some customers may comment on a rattle type noise at engine start-up.

Further inspection reveals the noise sounds like it is coming from the starter or flywheel.

Cause

GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Instructions

Verify the concern and contact one of the engineers listed below for further instructions.

Contact Information

Engineer Name	Phone Number
Steve Field	810-625-9931
Steve Zeigler	248-255-7027

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
8480028*	Engineering Information – Rattle Type Noise at Engine Start-Up	0.2 hr

*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.